

## Software history

**Note: The filename of the bin file may NOT necessary be the same as the model number.**

**The latest software solves the issues below:**

### **Version 38 (HTL2163B/05/12/51/61/78/79/93/F7)**

TV screen version info

**V38.25.07.140620A1**

Local Display version info (will show in following sequence)

- 1) Main Version: **V38**
- 2) RISC version: **140620A1**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V07**

- Bug improvement

### **Version 35 (HTL21x3/31x0/3142)**

TV screen version info

**V35.25.07.140620A1**

Local Display version info (will show in following sequence)

- 1) Main Version: **V35**
- 2) RISC version: **140620A1**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V07**

- Reduce auto standby time to 15 minutes from 30 minutes
- Resolved source switching issue with NFC tapping
- Minor bug fixes

### **Version 27 (HTL21x3/31x0/3142)**

TV screen version info

**V27.25.07.140219A1**

Local Display version info (will show in following sequence)

- 1) Main Version: **V27**
- 2) RISC version: **14 0219A1**
- 3) TX version: **V25**
- 4) RX version: **V25**
- 5) Touch Panel version: **V07**

- Resolved HDMI CEC related issues
- Fixed audio interruption noise when selecting sound modes