

Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPN11E 2.07 *(Date published: 2011-09-06)*

- Sound distortion on analog channels with NICAM stereo. (Only applicable to country, Russian Federation)

TPN11E 2.05 *(Date published: 2011-01-13)*

- OSD translation error for Russian language is corrected.
- Colour interference while watching TV channel broadcast in SECAM video standard.
- Picture flickers when you playback the video content from a VHS-VCR through EXT 1 (SCART) connection.
- TV will automatically switch to standby or out of standby.

TPN11E 2.04 *(Date published: 2010-07-19)*

- TV has cracking sound or no sound after channel change.

TPN11E 2.03 *(Date published: 2010-06-02)*

- Initial production software.