

Software history

Philips 2K20 32PHS6605 & 68x5 & 6905 - range

TPM207E_202.005.004.001– Date: 2022/11/14

- Fix for failing channel selection from TV Guide
- Fix for HBBTV playback taking long time to load
- Fix for no response on remote control key presses

TPM207E_202.003.236.011– Date: 2022/07/28

- Improvements for system stability
- General improvements

TPM207E_202.003.236.001– Date: 2022/06/01

- Improvements for system stability, reboots
- Fix for Netflix, YT and Prime video playback issue

TPM207E_202.003.228.001– Date: 2021/03/07

- Improvements for system stability
- General improvements

TPM207E_202.003.188.011– Date: 2021/10/18

- Improvements for WiFi connection issue
- Improvements for system stability
- Fixed HDMI A/V signal via Vodafone STB
- General improvements

TPM207E_202.003.181.001– Date: 2021/08/09

- Solutions for playback issues in local VoD services (TV2 Play, NPO Start , Viaplay, OTTPLAYER, M7)
- Improvements for system stability
- General improvements

TPM207E_202.003.116.011– Date: 2021/04/06

- Solutions for playback issues in local VoD services (Divan TV, All4 + My5)
- Fixed Slovenian SRT subtitles
- Fixed A/V signal after restarting the HDMI source
- Improvements for system stability
- General improvements

TPM207E_202.003.085.001– Date: 2021/01/26

- Improvements for system stability
- Solutions for playback issues in local VoD services (Cmore and Bloomberg)
- General improvements

TPM207E_202.003.043.011– Date: 2020/12/08

- Improvements for system stability
- Fix for Netherlands app "NPO Start"
- General improvements

TPM207E_202.002.238.011– Date: 2020/09/16

- Initial firmware for 6905 series
- General improvements

TPM207E_202.002.186.011– Date: 2020/08/01

- Mediastate Law compliance
- General improvements

TPM207E_202.002.078.011– Date: 2020/06/16

- Initial version for /62 CTN
- General improvements

TPM207E_202.002.026.011– Date: 2020/04/16

- Initial firmware for the 2K20 32PHS6605 & 68x5 range