Software History

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPN152E_003.160.000.000 (Date published: 2018-07-23)

• TV reboot after press on EPG RC key - Slovenia.

TPN152E_003.140.000.000 (Date published: 2017-09-01)

• TV reboot with local DVB-C signal - Romania.

TPN152E_003.130.000.000 (Date published: 2017-01-16)

• Solve picture flickering (HDCP2.2 protected content).

TPN152E_003.120.000.000 (Date published: 2016-12-15)

- Channels were missing after overnight standby update Croatia.
- TV switches to another regional broadcast transmitter UK.
- Channel names are missing Slovenia.
- Correction of translation error Russia.
- Improvement Slow TV start up/TV stability.
- Improvement DVB-S channel installation.
- Further improvement TV reboot/Hang up.
- eUM content update.

TPN152E_003.090.000.000 (Date published: 2016-06-30)

• DVB-S channel name incorrect.

TPN152E_003.070.000.000 (*Date published: 2016-05-31*)

• Enable HEVC service in advanced scan.

TPN152E_003.060.000.000 (Date published: 2016-04-27)

- **YouSee** network frequency changed from 143MHz to 450MHz, Denmark.
- Update in Channel list (Swiss-German) SFR info HD.
- Solves onscreen keyboard only able to accept numeric key when entering Wifi encryption mode.
- Stability improvement.
- Improves PQ in DVB-T HD content.
- Improvement on **Voo** audio playback when connected to setup box.

TPN152E_003.050.000.000 (Date published: 2016-03-11)

• To fix 6 am TV wake up issue.

TPN152E_003.040.000.000 (Date published: 2015-12-22) (Italy H set only)

• To fix the channel ordering issue in Italy.

TPN152E_003.010.000.000 (Date published: 2015-12-07) (T set only)

• To add Freeview HD in UK.

TPN152E_002.013.000.000 (Date published: 2015-09-30) (T/K set only)

• Initial production software for T & K models.

TPN152E_002.010.000.000 (*Date published: 2015-09-14*) (*H set only*)

• Initial production software for H models.