

Software history (HTL2160/12, HTL2160C/12, HTL2160S/12, HTL2160W/12, HTL2160T/12, HTL2160G/12)

Note:

- The filename of the bin file may NOT necessarily be the same as the model number.
 - Each release contains all solutions identified in the earlier version.
 - After upgrading with the latest firmware, disconnect the device from power supply. Wait for a few minutes and then reconnect to power supply.
 - After updating the device, some settings such as HDMI-CEC might be erased. Refer to the user manual for the set-up after updating the device.
-

The latest software solves the issues below:

NOTE: Each release contains all solutions identified in the earlier version.

V.20

- Added new feature for better sound personalization: remember last audio setting

MPEG v16S

- Fixed the bug related to auto standby mode.