

Software History

Warning:

This software is only for TV set with TPN149E_X.XXX.

Always check the current software in your TV set before you update the software. Uploading the wrong software to your TV set may cause malfunction to your TV set.

NOTE: Each release contains all solutions identified in the earlier version.

The latest software solves the issues below:

TPN149E_V3.000 (Date published: 2014-07-28)

- Add PVR EDFU.

TPN149E_V2.100 (Date published: 2014-07-07)

- Feature implementation: PVR function.
- Fix issue: TXT improvement.

TPN149E_V2.090 (Date published: 2014-06-13)

- Fix issue: [Italy] channel loss.
- Fix issue: No translation string "The former channel is moved to".

TPN149E_V2.080 (Date published: 2014-05-23)

- Cannot reorder DVB-S in favorite list.
- PQ issue on Analogue channels.
- Fix issue: Jumping channels by itself in channel list & favorite list.
- Fix issue: TV lost all digital channels in standby mode.
- Fix issue: [Italy] 191.5MHz and 786MHz channel loss issue.
- Issue fix: [Portugal] DVB-T reboots sporadically.

TPN149E_V2.070 (Date published: 2014-04-23)

- E-sticker: Add e-sticker icon for extern model.
- Fix issue: Estonia cracking sound issue for ATV.
- Fix issue: Austria UPC jumping channel by itself.

TPN149E_V2.060 (Date published: 2014-04-09)

- Fix issue: UK channel sorting issue.
- Fix issue: CI CAM pin code message fixed.

TPN149E_V2.050 (Date published: 2014-03-25)

- Help content not as the same as SPEC
- Fix issue: Search the DVB-C channel in Norway/Belgium by quick/advance scan, TV lost DTV channel.
- Fix issue: Use Local joystick, cannot switch to Satellite/TV.
- Fix issue: Bass/Treble values do not be stored after power off/on.
- Fix issue: Set will reboot after power off about 15min.
- Fix issue: [UK] in DVB-T full scan finished, ATV source picture format =super zoom then picture shift

function icon is display disable.

- Fix issue: Menu language lost Arabic.
- Fix issue: K-model channel scan issue.
- Fix issue: change string in SAM modeà immrdiately -> immediately

TPN149E_V2.040 (*Date published: 2014-03-17*)

- Fix issue: Character set for Cyrillic.
- Fix issue: Dutch language translation.
- Prevent action: Sync 2K13 set solution of startup reboot issue.
- Prevent action: Sync 2K13 set DVB-T Modena reboot issue when channel scan in Italy.

TPN149E_V2.030 (*Date published: 2014-02-27*)

- Default value update: Add Greece/Ireland in H/88 country list.
- Satellite scan mode change: Remove scan mode page for K model.

TPN149E_V2.020 (*Date published: 2014-02-21*)

- Default country/language value in UK/English for H/88 model.
- Remove set pin code menu and parental rating Age none in UK.

TPN149E_V2.010 (*Date published: 2014-01-24*)

- Initial production software for H & T models.