#### Software history

#### Main modifications

#### Each release contains:

- All solutions identified in earlier versions
- Improved connectivity to improve compatibility with other external devices

# Q591E\_0.103.0.0

• Solution for problem in south Italy(area Naples due to analog switch Off)

# Q591E\_0.102.0.0

• Solution for the video format that was not compatible for TELEMADRID HD.

# Q591E\_0.101.0.0

- enabling the MPEG4 reception for Italy.(Only for "xxPFLxxx3H" sets)
- Improvement use of free to air common interface card to decode mp4 digital channels.

# Q591E\_0.100.0.0

- implementation to switch off the overnight update.
- Regression caused on HDMI has been resolved.

# Q591E\_0.97.0.0

• Solution for picture drops when watching digital broadcasts in the United Kingdom.

### Q591E\_0.94.0.0

- audio issue solved when switching between HDMI sources.
- Optimalisation Audio SPDIF for HTS3367

### Q591E\_0.93.0.0

- Upgrade Madrid solution.
- Improvement for Riks-TV.
- Improved picture quality via availability of more colors.(color gamut)

### Q591E\_0.91.0.0

- Solution for the Madrid Broadcast issue.
- Improvement digital channel reception La7 DVB payTV channel Italy.
- DGTVi approved.

### Q591E\_0.89.0.0

- Improvement of Teletext. (no longer mixed pages or skipped parts)
- Solution for loosen channels overnight in Denmark.
- Reboot of the 42PFL9803D/10 after switching to the HDMI(Philips 1080) solved.

# Q591E\_0.83.0.0

- replaces all previous releases, including Q591E\_1.58.14.0.
- problems with installation algorithm for DVB-T UK solved.
- audio problems with certain STB devices solved.

# Q591E\_0.58.14.1

- Improvements for DNLA(decrease time to display thumbnails)
- Improvements DVB-T for France(region with the Belgian boarder)

#### Q591E\_0.58.11.0

• Improvement of the OSD after start-up.

### Q591E\_0.58.8.0

- Missing of information on TXT pages has been solved.
- Improved settings when identifying the source as a 'PC'.
- Resolving the fact that mouse movements lag behind.
- Solution about disappearing subtitles with DVB-C.
- Sporadically no picture on DVB-C channels with specific CAM's and when starting up the TV, has been solved.

# Q591E\_0.58.5.0

- Improvement of the connection via HDMI with Bose system.
- Improvement of stand-by behaviour.
- Improvements for EPG behavior in UK.
- Functionality added for Australia and Finland.
- Improvement scroll behavior remote control.
- supports MPEG4 in Spain.

# Q591E\_0.25.26.1

• Improved channel reception in Spain.

# Q591E\_0.25.24.1

• Improved black impression.

# Q591E\_0.25.21.0

- A 1080p 60Hz type of input signal does no longer show flashes on screen with this software upgrade.
- The Common Interface functionality is now enabled for the UK with this software upgrade.
- Possible picture judder with MPEG4 signals is solved with this software upgrade.
- While the TV relaunches its software during normal use, strange picture and sound artefacts no longer appear, with this software upgrade.