

Philips Software Upgrade for Blu-Ray players

Introduction


Philips offers software upgrade capability for your Blu-Ray. After you have completed the software upgrade, your Blu-Ray will typically perform better. What improvements are made depends on the software you are using as well as the software your Blu-Ray contained before the upgrade. You can execute the software upgrade procedure yourself. Be aware that the content of this document is addressing technical and software skilled users.

For the procedure you will require:

- > A personal computer with web browsing capability
- > An archive utility that supports the ZIP-format (e.g. WinZip for windows or Stuffit for Mac OS).
- > A USB Flash drive with at least 100M of memory.

How to check your software version:

To check your software version, cursor down to Setup and then select Advanced Setup using the cursor and OK buttons on your remote. Then select Version Info to view the version of software in your unit. All of the features shown in the example below may not be present in your model.




If the version number shown on the website is greater than the version shown on your player (as in the example above right), select Software Update in the Advanced Setup menu. If the version is the same, you cannot upgrade your player.

Software upgrade procedure:

Note: If you are connected to the internet, you can download the latest software directly to your player.


If you are not connected to the internet, download the latest software and follow the procedure below.

1. Download the *.zip file for your model and extract the *.bin file.
2. Load the *.bin file to the root directory of the USB drive.
3. Make sure the player does not have a disc in the tray.
4. Press the Menu button on the remote followed by Advanced Setup, Software Update, USB.
5. Insert the USB drive and select Yes to upgrade when prompted. The version shown here may be different from the version you are loading.



6. The software upgrade will start. Do not remove power to the player until the update is complete.

The following screens will appear during the software update. This update may take some time to complete. Do not remove power or attempt to turn the unit off during the update.



Software History:

Version	Problem solved
1.10.04	> VUDU HD added
1.26.01	> Upgrades Netflix to V3.0
1.32.52	> Add CloudTV. > Add vTuner Podcast feature. > Add 3D setup to allow selection of Frame Sequential, Side by Side or Checkerboard. > Tag Games opening display changed. > CloudTV icon delected from the Music and Video category.
1.32.55	> Connection test added.
1.32.57	> Cloud TV does not connect.
1.60.13	> Replaced Block Buster ICON > Screen splits in two when playing VUDU 3D content on some VIZIO TVs. > Added trademark sentence for Windows Media DRM